Creation of Work Groups

The MAMCoP subgroup and the MOCOPA® subgroup have been working on a number of operation and safety related issues which affect today's metering activity. These issues are generally unclear and require debate and resolution otherwise the threefold increase in metering activity associated with smart metering they will cause considerable extra cost and disruption to customers and industry stakeholders.

These groups have each given an initial view of many issues. Some can be taken forward independently, but others require further consideration in a smaller more focused debate. For the next phase of work it is proposed to create working groups to focus on these related issues. Tom Chevalier (AMO) and Paul Smith (ENA) in discussion with Ofgem representatives have considered the breadth and priority of issues leading to the proposal to create the following working groups.

The working groups are expected to use any material already in existence, including existing company specific guidance as well as drawing on expertise outside the group as appropriate. The groups should be focused on *delivering solutions*, whether they be proposals to publish 'best practice guidance' or changes to formal governance or regulation.

It is anticipated that each group will meet at least four times over a four month period (Mar-Jun 2011) with email exchanges in between. The first meeting for the two gas groups is proposed for **28th March**, at SBGI's offices at Kenilworth and for the two electricity groups on the **17th March**, at Gemserv's offices. It is intended that the groups will meet separately but in parallel.

1.1. Gas metering electrical issues

At the Dec 2010 MAMCoP sub-group meeting a number of issues were discussed associated with electrical aspects of gas meter installation. The discussion demonstrated a lack of understanding of some issues and a significant variance in practice across participants.

The aspects considered to be included in this group are:

- Gas/electricity pipe/cable proximity
- Insulated inserts in gas services
- Temporary earth strapping (when changing meters)
- Use of 'volt sticks'
- Disconnection/re-connection of customer bonds
- Extension (or not) of electrical bonding cables as result of gas meter moves
- Bonding arrangements in multi-occupier premises (IGEM G/5 working group)

It is proposed that the group should be no more than 6-8 members, including representatives from:

- Meter Asset Managers
- Gas Transporters
- IGEM and/or G/5 working group
- The IET (wiring regulations) and/or Electrical Safety Council
- HSE

1.2. Gas meter accessibility

A number of the issues are related to access to the meter:

- Meter heights
- Meter inaccessible, e.g. back of kitchen cupboard
- Flat meter in shop below
- Access to communal meter cupboards
- Permali meter boxes (although being resolved through unsafe sits panel)

Other meter installation issues, e.g. outlet flexes

It is proposed that the group should be no more than 6-8 members, including representatives from:

- Meter Asset Managers
- Gas Transporters
- Gas suppliers
- IGEM and/or G/5 working group
- Ofgem

Although this group is designed to be focused on gas, the solutions can be expected have a 'cross over' into electricity.

1.3. Meter Operator to electricity distributor fault reporting

To move forward the proposals to:

- Define a replacement (or enhancement) to the existing DTC dataflow D0135 with a flow which would actually meet the business needs
- Define a new response/update flow from Distributor to reporting party (meter operator/supplier/DC) to confirm existing report when reported by phone, and provide information of completion of the rectification
- Work in conjunction with DCUSA, obtaining feedback from their information request
- Raise appropriate change within the MRA through IREG to refine the proposed flow
- Subsequent work to document examples of problems which need reporting under each group, expect this it be a guidance document under MOCOPA[®] governance

It is proposed that the group should be no more than 6-8 members, including representatives from:

- Meter Operators
- Distribution Businesses
- ERA supplier
- MRA IREG
- DCUSA

1.4. Meter Tails

To move forward the proposals to develop national guidance for the:

- sizing of meter tails
- · cut-out fuse sizing

It is proposed that the group should be no more than 6-8 members, including representatives from:

- Meter Operators
- Distribution Businesses
- Electrical Safety Council or IET

1.5. Existing working groups

MOCOPA® has already established two working groups:

- Outcomes from the ESFRS report, such as the proposal for a label located near the electrical intake position. Consideration of a meter positions in the communal areas of buildings in multiple occupancy.
- Issues surrounding the inspections of customers intake equipment.

These issues were discussed at the stakeholder workshop on the 8th Feb which has informed the groups on how to take the issues forward.

As result of the stakeholder workshop the damaged meter box consideration will be next progressed with suppliers.


1.6. Further groups

Other groups may include gas structured non-urgent communication, need to de-energise multiple customers to work safely. Without more resource coming forward, then realistically these aspects may follow on when the above work completes.

Attached is a spreadsheet which lists all the issues which are under consideration. Some are being more actively considered than others. If there any further items or you feel the priorities are incorrect, then please contact us.

1.7. What next?

We already have some volunteers for these groups (see spreadsheet). If you would like to participate in any of these working groups or discuss this work, please contact Tom Chevalier (01525 862870) Tom.Chevalier@PowerDataAssociates.com or Paul Smith (07717 433472) paul.smith@energynetworks.org.



Gas14	Gas13	Gas12	Gas11	Gas10	Gas8 Gas9	Gas7	Gas6	Gas5	Gas4	Gas3	Gas2	Gas1	Issue
Insulation joints	Permali meter boxes	Identify new connections with MPR	Legacy Metering Arrangements	Two yearly inspections	Meter in asbestos box Other meter installation concerns	Meter box size	Suitability of semi-concealed meter b Are semi-concealed meter boxes appropriate for use? Consider wingress, electronics, radio receptions and the semi-concealed meter beautiful appropriate for users.	Damaged meter boxes	Meter inaccessible	Meter Height	Communal Cupboards	Flat meter in shop below	Title
Clarity on the provision of insulation joints and metal service pipes in advance of ECV	Concern about suitability of Permali meter boxes	Identify new connections with MPRN Use of label on all new connections	Review of G-1 to define the 'end of the network'	Issues associated with desire to remove global requirement for two year safety checks	Meter box of asbestos construction Other issues, incl meter in concrete floor, outlet flexes	Meter box not of appropriate size for meter	b Are semi-concealed meter boxes appropriate for use? Consider water ingress, electronics, radio reception	MAM or GT find damaged customers'	Meter fitted in premises, but in an inaccessible location	Location of new meter installations	Access to communal metering cupboards	Access to meters inaccessible to customer	Brief description
Gas Old Chestnut 2.14	Gas Old Chestnut 2.13	Gas Old Chestnut 2.12	Gas Old Chestnut 2.11	Gas Old Chestnut 2.10	Gas Old Chestnut 2.8 Gas Old Chestnut 2.9	Gas Old Chestnut 2.7	Gas Old Chestnut 2.6	Gas Old Chestnut 2.5	Gas Old Chestnut 2.4	Gas Old Chestnut 2.3	Gas Old Chestnut 2.3	Gas Old Chestnut 2.2	Source
MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	Forum for debate
ENA SMOG reviewing requirements	NGG developing approach with gas unsafe sits panel	Occurring, remind MAMs not to remove	under consideration through IGEM - but need to consider MAM impact not just 'technical'	See Ofgem consultation as result of BG request	under consideration under consideration	BS determines size for new boxes. Existing boxes either OK or may need changing	MAMCoP sub-group not keen on them, but smart meters are being fitted in them. Could the industry stop new ones?	Discussion paper prepared - workshop scheduled in Feb11	under consideration - hard	Debated - consider proposal to introduce develonded develonange into MAMCoP - but how to capture group GT?	debated	debated	current status
Action NGG Develop through working group	Action NGG	Action AMO		pending Ofgem consult	develop through working group			Action AMO	develop through working group	develop through working e group	develop through working group	develop through working group	state
3	I	_	_	Z		_	г	Z	3	3	_	≤	Priority
N	-	ω	ω	ω	ωω	ω	ω	2	8	_	ω		Timescale
gas/electrical issue	meter accessibility				meter accessibility			×	meter accessibility	meter accessibility	meter accessibility	meter accessibility	Grouping

Elect1	Gas27	Gas26	Gas25	Gas24	Gas23	Gas22	Gas21	Gas20	Gas19	Gas18	Gas17	Gas16	Gas15	İssue
not used	Reporting of non-urgent issues	Extension (or not) of customer earth	Disconnection/re-connection of cust	use of volt sticks	meter change temporary bonds	Bonding arrangments in flats	Chargeable items	I&C issues	iGT data flows	ECV inoperable or missing	Water ingress incidents	Prime & sub-deduct metering	Electricity/gas proximity	Title
	Reporting by MAM to GT of urgent issues occurs by phone. However there are some less urgent issues that could be more effectivly communicated in a dataflow	Extension (or not) of customer earth I The correct approach to be adopted when customer earth bonding needs extending as result of mater moves	Disconnection/re-connection of custc The skills/ability of gas meter operative to disconnect/re-connect customer earth bonding when found in wrong place, or needs moving to allow pipework changes	Concern raised at sub-group about use/purpose of temporary bonding	Concern raised at sub-group about use/purpose of 'volt sticks'	clarify requirements of bonding for IGEM G5	ost money, how he cost fall?	A range of I&C issues have been identified, although these are low priority for consideration	Exchanging data for iGT installed meters add complexity	following a major incident A protocol between GT/MAMs was agreed last year, need to confirm it is operating successfully	Concern that the current competitive market does not support the rapid restoration of metering equipment	These are not currently allowed for new installations, the responsibilities need review as part of Ofgem consultation	Gas requirements are to keep a distance from electric equipment. The requirements are not reflect in electricity documents. Need to clarify the actual requirement.	Brief description
	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	lgem G/5	MAMCoP sub-group	Gas Old Chestnut 2.20	Gas Old Chestnut 2.19	Gas Old Chestnut 2.18	Gas Old Chestnut 2.17	Gas Old Chestnut 2.16	Gas Old Chestnut 2.15	Source
	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	MAMCoP sub-group	Forum for debate
	raised	Varying views	Varying views	Varying views	Varying views	questions raised as result of sub-group work	matrix created, needs populating. ENA SMOG completed gas, electricity to be completed. Certain items need MO input	later consideration	under consideration	NGG to check their approach WWU reported no MAM has approached	Needs views from ENA SMOG as to what Action SMOG they would like MAMs to provide	await Ofgem consultation	Jim Sibley to write - which can be reviewed by MOCOPA	current status
		develop 'best practice' through workgroup	develop 'best practice' through workgroup	develop 'best practice' through workgroup	develop 'best practice' through workgroup	clarify understanding/requirem	Action ENA, Action AMO	Parked	Parked	Action NGG	Action SMOG	pending Ofgem consult	Action NGG Develop through working group	state
×	3	≤	3	Z	Z	Z	I	_	_	_	_	r	r	Priority
×	Ν	4	ပ ဌ	2	ر 9	2		ω	ω	ω	ω	ပ		Timescale
		gas/electrical issue	gas/electrical issue	gas/electrical issue	gas/electrical issue	gas/electrical issue							gas/electrical issue	Grouping

Elect16	Elect15	Elect13	Elect11	Elect10	Elect9		Elect7	Elect6	Elect5	Elect4	Elect3	Elect2	Issue
Cross polarities and ESQCR reportin HSE concern that not all issues are registered and reported through ESQCR EID system	MO reporting issues to Distributors	MOCOPA® safety information	Cage terminals	Meter Height	Flat meter in shop below Communal Cupboards		Rising & Lateral services	Earthing - existing connections	Earth Connection - new connections Clarify roles/responsibilities for provision of earth connections	Fused neutrals	Metal clad cut-outs	Inadequate Meter Boards	Title
HSE concern that not all issues are registered and reported through ESQCR EID system	VT/CT certs) is being provided by Distributors under MOCOPA® Improve the reporting and logging of issues identified by MOs	Not all safety and operational information is being provided by Distributors under MOCOPA® Not all coordings information (c.g.)	Concern over use of cage terminal to securely capture cables	Location of new meter installations	Access to meters inaccessible to customer Access to communal metering curboards		existing connections Clarity of responsibility between Distributor and building owner	Clarify roles/responsibilities for provision of earth connections at	Clarify roles/responsibilities for provision of earth connections at new	clarify ESQCR reporting and reiterate current practices	Agree safe methods of working and/or	How customer replaces a rotten or otherwise inadequate 'meter board'	Brief description
Elect Old Chestnut 2.15	Elect Old Chestnut 2.14	Elect Old Chestnut 2.12 Elect Old Chestnut 2.12	Elect Old Chestnut 2.10	Elect Old Chestnut 2.9	Elect Old Chestnut 2.7 Elect Old Chestnut 2.8		Elect Old Chestnut 2.6	Elect Old Chestnut 2.5	Elect Old Chestnut 2.4	Elect Old Chestnut 2.3	Elect Old Chestnut 2.2	Elect Old Chestnut 2.1	Source
MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®		MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	Forum for debate
Chasing remaining MOs to register and report regularly MOCOPA® developing CP to add requirements into MOCOPA®	requirement through ENA and considering a Distributor audit regime Developing hierarchy of issues and reviewing reporting/logging mechanisms	under consideration for adding into BS7856 Enhanced the website, broadened requirement through ENA and considering a Distributor audit regime	under consideration for adding into BS7856	CP rejected. Reasons for rejection being considered and will review in Jan 2011 mtg	under consideration. CE Electric preparing straw man under consideration	http://epr.ofgem.gov.uk/index.php?pk=doc 600733 may provide guidance to others AMO considered further on 17Feb11	mtg Principle accepted that Distributor and building owner will review each case individually. UKPN	ring CP rejected. Reasons for rejection being considered and will review in Jan 2011	CP rejected. Reasons for rejection being considered and will review in Jan 2011	Current practices of replacement confirmed. No ESQCR reporting currently required - closed	Principle agreed. AMO/ENA to document	Principle agreed, if cut-out attached must be Distributor, if meter only then MO. AMO to document	current status
Action MOCOPA© CP approved for May11 release AMO members circulated Oct-Dec10 report	Distributors Develop in workgroup		Action BSI	Action AMO to redraft CP with words acceptable after previous rejection	Action CE Electric	u	Action AMO to circulate concerns	Action UKPN/RP	Action UKPN/RP	Closed	Action AMO/ENA	Draft CP discussed at MOCOPA RP (Mar11). Action AMO/MOCOPA to	state
≤	Ι .	- I -	· -	≤	⊢ ≤		Z	Z	Z	×	≤	_	Priority
_	×		ω		3 2		8	<u> </u>	_	×	_	_	Timescale
review panel	reporting	review panel		review panel				review panel	review panel				Grouping

Elect30	Elect29	Elect28	Elect27	Elect26	Elect25	Elect24	Elect23	Elect22	Elect21	Elect20	Elect19	Elect18	Elect17	Issue
Multiple customer isolation	9 Looped Neutrals	8 Multi-way cut-outs	7 Meter tail sizes	6 Fuse sizes	5 Varying Distributor requirements	4 Colour of meter tails	3 Label CT/VT details	2 Access to meters in substations		0 Electricians breaking seals	9 Two yearly inspections	8 Meter box size	7 Damaged meter boxes	
Replacing a single meter may require interruption of supply to another customer(s). Several customer fed from one cut-out. What are the practical and legal issues?	Safety issue identified where neutrals are looped for more than one customer	The special locking of multi-way cut- outs should be reviewed as to whether it is necessary	Clarity required over the size of meter tails, and whether these are changed when not already 25mm2, particulally between cut-out to meter	quired over the size of cut-out	Distributors have differing requirements prior to approving meter operatives in their area	Raised by MOCOPA® Auditor particular MOCOPA® RP issue in multi-customer installations	Distributor to provide an accessible label on all new/changed CT/VT metering arrangements	Ensure new meter locations are accessible to MO and customer	Intervaluing DETS Identify new connections with MPAN Label all new connections with MPAN to Elect Old Chestnut 2.20 assist all parties to know correct premises	Discussed at DCUSA in 2009. Promote the FAQ document. Consider	Issues associated with desire to remove global requirement for two year safety checks	There is no BS for electricity meter boxes, therefore smaller boxes can be fitted.	MO or Distributor find damaged meter box - how is it resolved?	Brief description
MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	Elect Old Chestnut 2.21	Elect Old Chestnut 2.20	Elect Old Chestnut 2.19	Elect Old Chestnut 2.18	Elect Old Chestnut 2.17	Elect Old Chestnut 2.16	Source
MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA [®]	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	Forum for debate
Discussed 13jan11. Initial approach agreed. Combine with Elect29	Discussed 13jan11. Initial approach agreed. Combine with Elect30	Review as part of guidance about 'unsuitable' cut-out designs	Under consideration	Draft CP to clarify obligation on Distributor Develop in workgroup to advise and change fuses if required. ENA SMOG considering	Reviewing and seeking to remove or consider inclusion as generic requirement in MOCOPA®	CP confirmed, incorporated into MOCOPA@in Oct10	Proposal for label to be fitted being developed	agreed, but need to embed in Distributor design documents	under consideration	under consideration. ESC wrote to Ofgem pending Ofgem about knife switch	See Ofgem consultation as result of BG request	MOCOPA® approached BSI about developing new BS8567 to compliment existing gas BS, BSI setting group up.	Discussion paper prepared - workshop scheduled in Feb11	current status
Action AMO	Action AMO		Develop in workgroup	Develop in workgroup	Action ENA	Closed	MOCOPA® CP approved for May11 release		Action ENA	pending Ofgem	pending Ofgem consult	BSI called forst drafting mtg on 23mar11	Action AMO to discuss	state
Z	Z	S	Z	3	Ι	×	r	г-	_	٦	≤	۲	Z	Priority
N	8	ა უ	2	2 2*	-	×	ယ အ	ω	ω	2	ω ×	ω ×	ν ×	Timescale
		fuse/tail sizes	fuse/tail sizes	fuse/tail sizes			review panel				.,	-	•	Grouping

Elect40	Elect39	Elect38	Elect37	Elect36	Elect35	Elect34	Elect33	Elect32	Elect31	issue
Off peak load contactors	Plastic meter boxes internal to build		Customer equipment in meter box	ESFRS Report into cut-out fires	Provision of CT Meter Cabinets	Connection of non-whole current tails Clarity has been provided by the MOCOPA® review panel that the Distributor should connect tails very the connection is not whole current tails with the connection is not whole current tails with the connection is not whole current tails with the connection is not whole current tails.		Microgeneration back feed	Chargeable items	Title
Lack of clarity over ownership, responsibity and liabilities	Plastic meter boxes internal to buildir Concern riased by ESFRS that meter boxes internal to buildings particulalry on escape routes, should be fire	Traditionally meter boards had to confirm to certain requirements, e.g. fireproof. These requirements do not	Traditionally 'customer' equipment (e.g. DP isolator) has not been allowed in the meter box, yet the practice has varied. Consider and determine some rules or guidance	Interesting report, circulated to MOCOPA® parties for comment, will be considered as trigger for change	Some Distributors have stopped providing panels to affix metering. Clarity of approach is required	ik Clarity has been provided by the MOCOPA® review panel that the Distributor should connect tails where the connection is not whole current	Customers installation poor or inader When a meter operative determines customers' installation is poor, then the practical and legal issues of resolution	Increasing use of microgeneration leads to risk where cut-out fuse removed, but potential for voltage on customers side of metering	Resolving issues may cost money, how MOCOPA® RP much and where does the cost fall?	Brief description
MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	MOCOPA® RP	Source
MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	MOCOPA®	Forum for debate
Paper produced by AMO not time to discuss on 17Feb11 mtg	new 23 dec 2010	Await debate in BS8567 and use that as guidance for all meter/cut-out boards	Discussed on 13Jan11 meeting. Appears reasonable to split box into 4 quarters, one of which could be used for customer switch/fuse	Warning label considered, Onstream/ESC/ESFRS drafted. Considered on 8Feb11 workshop	Discussion paper prepared. Comments - action on ENA to raise as tech issue	CP drafted - AMO need to amend to reflect comments	Considered paper at 8Feb11 workshop	Under consideration	matrix created, needs populating. ENA SMOG completed gas & electricity. Certain items need MO input	current status
working group Action AMO - discussion document prepared	ESFRS to provide guidance. Action develop further in	pending BS8567		Action develop further in working group AMO members considering issues	. MOCOPA CP for RP needs revision	Action AMO to revise draft MOCOPA CP	Action to develop proposals further in workgroup	•	AMO members considered, need to feedback to ENA/Ofgemworkshop	state
Z	_	_	_	3	Z	3	3		Ι	Priority
2	2	Ν	N	2	2	N	2	N	-	Timescale
×	fire lable	×	×	fire lable			installation checklis			Grouping

