

350 Euston Road, Regents Place, London NW1 3AX

- 1: 020 7121 3700
- 1: 020 7121 3701

CONFIDENTIAL

22 June 2016

Ofgem 9 Millbank London SW1P 3GE

Initially by email stephen.beel@ofgem.gov.uk

For the attention of Stephen Beel

Dear Sirs

Income Adjusting Event pursuant to Amended Standard Condition E12-J3 of the offshore transmission licence (the "Licence") of Thanet OFTO Limited (the "OFTO"), relating to an offshore cable outage affecting the transmission assets

As notified to Ofgem on 24 February 2015, the OFTO suffered a major fault on the subsea cable of Export Circuit 1 (the "Cable") on 23 February 2015. The purpose of this letter is to notify the Authority that we believe that, in respect of relevant year 2 ending on 31 March 2016, the OFTO has incurred costs above the STC threshold amount of £1,000,000 due to this event.

ě	7			KING IL V. W.				
inst	ırer's rce M	asis of the dra loss adjuster ajeure" under event due to th	the STC and	(see Appendix /or an event	eared by the consider the Author	ler this fault to be nority should ap	and addressed to be within the meaning prove to be an inco	the of me
f								
1				Y. H.				
ŀ			Aller			-		-,
	6							
F								


We acknowledge that the Report is in draft form and that the Authority will require the final report before assessing the event in full. Kindly note that this letter is being shared with the Authority now in the interests of time.



350 Euston Road, Regents Place, London NW1 3AX



t: 020 7121 3700 f: 020 7121 3701







t: 020 7121 3700 f: 020 7121 3701

STRICTRLY PRIVATE AND CONFIDENTIAL

30 June 2016

Ofgem 9 Millbank London SW1P 3GE

Initially by email Yvonne.naughton@ofgem.gov.uk

For the attention of Yvonne Naughton

Dear Yvonne

transfer.

Thanet OFTO Limited (the "OFTO"): additional information in support of notices pursuant to amended standard licence condition E12 – J3

In your letter of 17 June 2016 you requested Gwynt y Môr OFTO plc to provide additional information to enable the Authority to fully assess the Income Adjusting Events in respect of the Gwynt y Môr OFTO. In anticipation of the similar request with regards to the Income Adjusting Event in respect of the Thanet OFTO (as notified to the Authority on 22 June 2016), the OFTO has put together certain supporting information to enable the Authority to start assessing the OFTO's claim relating to the offshore cable outage of 23 February 2015. We will continue to provide you with additional relevant information as and when it becomes available.

1.	Details of the major fault on 23 February 2015 on Export Circuit 1 ("EC1") and any previous failures/technical concerns with this cable.							
	Please see Appendix 1 for the	and supporting	report,					
	which was also submitted with the original	I notice, in relation to the fault submitted by the	OFTO to the					
	Authority on 8 April 2016. These documents provide the details of the fault occurring on 23 February							
	2015 and outline previously known cable i	ssues and how the OFTO addressed those pr	ior to asset					

2. An explanation of why the major fault constitutes an event of Force Majeure under the STC and what action, if any, you have taken under paragraph 8 of section G of the STC.

Force Majeure under the STC is defined to include any event or circumstance which is beyond the reasonable control of a party which results in or causes the failure of that party to perform any of its obligations under the STC, and includes any fault or failure of Plant and Apparatus which could not have been prevented by Good Industry Practice (each as defined in the STC).

The OFTO considers the cable failure in respect of EC1 to be within the meaning of Force Majeure for the following reasons.

Fault or failure of Plant beyond reasonable control of the OFTO

Plant is defined in the STC to include fixed and moveable items used in the transmission of electricity and would therefore include the EC1 cable.

In respect of the failure of EC1,	concluded (amongst other things) the following:			








t: 020 7121 3708 f: 020 7121 3701




The cable failure was concluded to be due to manufacturing defects. The fault (having occurred during the manufacturing process) occurred prior to asset takeover and was therefore beyond the reasonable control of the OFTO.

Good Industry Practice



The OFTO conducted comprehensive and detailed technical due diligence on all aspects of the transmission assets prior to asset takeover and continued to monitor the transmission assets (including EC1) post asset takeover. There was no indication of any problems in the region of the cable on which the failure occurred at any point prior to the failure.



The OFTO could not reasonably have known about the extent of the manufacturing defects or controlled the damage it was not aware of, either prior to asset transfer or in the period post transfer prior to the failure occurring. The OFTO took a proactive approach to due diligence on the cables

350 Euston Road, Regents Place, London NW1 3AX t: 020 7121 3700 f: 020 7121 3701



3.

4.

The OFTO acted, at all relevant times, with the level of skill, diligence, prudence and foresight that would reasonably and ordinarily have been expected from a person in the OFTO's position.
Effect on STC obligations
The failure in respect of EC1 resulted in the failure of the OFTO to perform its obligations under paragraph 2.1.1 of Section C of the STC in respect of the cable.
Actions taken by the OFTO under paragraph 8 of Section G
provides a 24/7 control room services to the OFTO The Control Centre received first indications of the network fault via remotely monitored SCADA, and this was initially notified by the control to the National Grid NETSO Control Centre by telephone. The standby engineer was sent to investigate on site and, following confirmation of the fault scenario, further contact with NETSO confirmed the outage requirement via issue of a formal Transmission Status Certificate ("TSC") that was circulated by email between the parties. The preparation and issue of the TSC included initial sharing of basic information about likely prognosis.
A repair plan was put in place to diagnose the exact cause of the fault and to carry out rectification works. Pursuant to the failure on EC1, the OFTO carried out successful repairs of the assets, managing variable considerations including time, safety, numerous stakeholders and tidal and weather conditions, whilst at all times using all reasonable efforts to control and minimise costs. The main activities involved in repairing the cable included locating the fault site, tendering for the repair work, preparing and applying for the repair marine licence, taking out additional insurance to cover the works and then carrying out the actual cable repair and jointing work.
Throughout the implementation of the repair work, informal dialogue was maintained with NETSO regarding the status of the network. This mainly comprised telephone conversations between the OFTO (site and control centre) and the NETSO control centre. As the repair approached completion and preparations for re-commissioning were finalised, formal processes of raising further TSCs were undertaken to allow the return to service of the assets.
Full availability of EC1 was restored on 7 July 2015.
A detailed explanation as to how the amount of £11.7m has been calculated, including:
a. a breakdown of the costs incurred as a result of each IAE; b. an explanation of each cost and how the cost is a consequence of the event including costs spent 'directly managing the repair'; and c. invoices to support each cost.
Please see Appendix 2 for this information in relation to EC1 fault.
We are obliged to publish the Notices. Can you please identify any Information in your revised submissions that you consider is confidential.

THANET **OFTO**

350 Eusten Road, Regents Place, Lendon NWI 3AX

1: 020 7121 3700

1: 020 7121 3701

Should you require additional information to enable you to process these claims, please do not hesitate to contact me.

Yours faithfully

Simon Rooke On behalf of

Thanet OFTO Limited

Enc.

report for Export Circuit 1 fault

Appendix 1: report for Export C Appendix 2: Export Circuit 1 IAE cost information and supporting documentation Appendix 3: Original IAE Notice for Export Circuit 1 with proposed redactions

Appendix 4: Additional information in support of the original notice with proposed redactions