

## **Gas Safe Register Technical Bulletin Index**

## Issue number 010

## 8 December 2009

TB No.	Formerly	Gas Safe Register Technical Bulletin Index Subject	Publication Date	Status
TB 001	-	The Gas Industry Unsafe Situations Procedure 6 <sup>th</sup> edition	01.10.09	Current
TB 002	TB 204	Reporting of dangerous gas fittings – Reporting of Injuries, Diseases and Dangerous Occurrences Regulations (RIDDOR) – Regulation 6(2)	01.04.09	Current
TB 003	-	Built-over existing polyethylene (PE) gas services/service pipework – Safety concern	02.09.09	Current
TB 004	-	Managing risks from inappropriately installed medium pressure-fed domestic sized meter installations located in built-in or surface-mounted boxes	01.04.09	Current
TB 005	TB 184	Gas cookers in internal kitchens – Ventilation requirements	26.08.09	Current
TB 006	TB 127	Industry guidance for the checking of case seals and general integrity of room-sealed fan assisted positive pressure gas appliances	01.04.09	Current
TB 007	TB 150	Room-sealed (natural/fanned draught) and open-flued (fanned draught) appliance flues terminating within covered passageways (ginnells)	01.04.09	Current
TB 008	TB 200	Room-sealed fanned draught flue systems concealed within voids	01.04.09	Current
TB 009	TB 224	Sealing of extraneous pipe/cable entries to back boiler/circulator enclosures	01.04.09	Current
TB 010	TB 210	LPG regulator blockages	01.04.09	Current
TB 011	TB 233	The use of clips to secure vapour phase LPG hose and tubing to end fittings (UKLPG UIS 017)	01.04.09	Current
TB 012	TB 168	Visual risk assessment of gas appliances	01.04.09	Current
TB 013	TB 189	Air/Gas ratio valves	01.04.09	Current
TB 014	TB 214	Gas Work	01.04.09	Current
TB 015	TB 218	The requirement to install gas appliances (including cooking appliances) with flame supervision on all burners in flats and other multi-dwelling buildings	01.04.09	Current
TB 016	TB 231	Room-sealed flue/chimney terminations – Possible nuisance from fumes and the use of plume management kits	01.04.09	Current
TB 017	TB 235	HSE issues safety alert on gas appliance flues in ceiling voids	01.04.09	Current
TB 018	-	Glow-worm 'xi' range of boilers – Product modification and servicing reminder	27.04.09	Current

TB No.	Formerly	Gas Safe Register Technical Bulletin Index Subject	Publication Date	Status
TB 019	TB 170	British Standard 7967 Carbon monoxide in dwellings and the combustion performance of gas-fired appliances	01.04.09	Current
TB 020	TB 211	ACS combustion performance assessment (CPA1)	04.12.09	Current
TB 021	TB 228	The Gas Safety (Installation and Use) Regulations 1998 - Certificate of Exemption No. 1 of 2008	01.04.09	Current
TB 022	TB 185	Installation of previously used domestic gas cooking appliances	01.04.09	Current
TB 023	TB 154	Condensing boiler installation assessment procedure – England and Wales	01.04.09	Current
TB 024	TB 199	Condensing Boiler Installation Assessment Procedure – Scotland	01.04.09	Current
TB 025	TB 229	Contractor responsibilities when disconnecting and reconnecting gas cooking appliances fitted with a bayonet fitting, or other self-sealing connectors	01.04.09	Current
TB 026	TB 220	Effect of fans on open-flued gas appliances – Advice for non-gas operatives	01.04.09	Current
TB 027	TB 173	Domestic heating compliance guide & non-domestic heating, cooling and ventilation compliance guides	01.04.09	Current
TB 028	TB 007	Electro-osmotic damp-proofing systems	01.04.09	Current
TB 029	TB 011	Air supply from roof spaces	01.04.09	Current
TB 030	TB 022	Chimney terminations for decorative fuel effect (DFE) gas appliances	01.04.09	Current
TB 031	TB 024	Gas pipework identification – colour coding	01.04.09	Current
TB 032	TB 028	Potterton Prima 'C' compartment installation	01.04.09	Current
TB 033	TB 030	Valliant - Pressure loss through appliance gas valves	01.04.09	Current
TB 034	TB 040	Open-flued appliances in bathrooms - a "potted history"	01.04.09	Current
TB 035	-	Carrying out gas work on an waterway craft	01.04.09	Current
TB 036	TB 041	Fixed hobs and ovens – Flexible gas supplies	01.04.09	Current
TB 037	TB 042	Cannon Coalridge balanced-flue gas fire	08.12.09	Current
TB 038	TB 044	Gas fires and precast flue systems	01.04.09	Current
TB 039	TB 051	Warm Air Heaters - The history of return air arrangements for open-flued appliances	01.04.09	Current
TB 040	TB 053	Meter Box - Installation pipe sleeving	01.04.09	Current
TB 041	TB 058	Multi-appliance ventilation	01.04.09	Current
TB 042	TB 060	Repairs following reported gas escapes	01.04.09	Current
TB 043	TB 064	Electrical work on gas appliances	26.10.09	Current
TB 044	TB 065	Retro fitting of FFDs on catering equipment	01.04.09	Current
TB 045	TB 066	Re-lighting existing gas appliances after carrying out a tightness test	01.04.09	Current
TB 046	TB 067	Gas tightness testing requirements	01.04.09	Current
TB 047	TB 068	Pre-cast chimney/flue cooler plates	01.04.09	Current
TB 048	TB 075	Gas Supply Rights of Entry Regulations 1996	01.04.09	Current
TB 049	TB 079	Spillage testing with decorative re-circulatory ceiling fans present	01.04.09	Current
TB 050	TB 080	Suitability of plasterboard within the builder's opening	01.04.09	Current
TB 051	TB 081	Ventilation of kitchens in catering establishments	01.04.09	Current

TB No.	Formerly	Gas Safe Register Technical Bulletin Index Subject	Publication Date	Status
TB 052	TB 088	Cleaning high efficiency heat exchangers	01.04.09	Current
TB 053	TB 091	Modular boiler installations	01.04.09	Current
TB 054	TB 096	Leakage of combustion products from positive pressure fan-assisted boilers	01.04.09	Current
TB 055	TB 099	Duties of Landlords	01.04.09	Current
TB 056	TB 100	Installation of open-flued appliances in domestic garages	01.04.09	Current
TB 057	TB 101	Passive stack ventilation	01.04.09	Current
TB 058	TB 102	Painted appliance cases	01.04.09	Current
TB 059	TB 201	Potential gas escapes on the stainless steel pliable or semi rigid gas meter connections	01.04.09	Current
TB 060	TB 104	Purpose provided ventilation (Domestic)	01.04.09	Current
TB 061	TB 105	Reducing the size of builder's openings and fireplace recesses	01.04.09	Current
TB 062	TB 109	The 'Benchmark' Scheme	01.04.09	Current
TB 063	TB 110	Carrying out gas work on leisure accommodation vehicles, residential park homes and holiday accommodation	01.04.09	Current
TB 064	TB 120	Gas safety concern - Widney, Nevada and Regency gas fires	01.04.09	Current
TB 065	TB 122	LPG Cabinet space heaters and the requirements of legislation	01.04.09	Current
TB 066	TB 129	Morco Model D-61B, 61E and G111E water heaters	01.04.09	Current
TB 067	TB 131	Carfield-Geminox Boilers – Inappropriate flue materials	01.04.09	Current
TB 068	TB 134	Open-flue chimney terminations in proximity to structures	01.04.09	Current
TB 069	TB 135	HSE Press release regarding replacing ductile iron gas mains	01.04.09	Current
TB 070	TB 140	Gas and electric appliances known to contain asbestos containing materials	01.04.09	Current
TB 071	TB 143	Checking the operating pressure of the meter regulator - Natural gas	01.04.09	Current
TB 072	TB 144	Separation distances between LPG cylinders and tanks and domestic oil tanks	01.04.09	Current
TB 073	TB 151	Glow worm Micron case seal modification	01.04.09	Current
TB 074	TB 152	Use of preformed pipe insulation for protection of gas pipework in concrete floors	01.04.09	Current
TB 075	TB 153	Glow-worm Micron boiler range – Product recall	01.04.09	Current
TB 076	TB 156	Electronic records and signatures	01.04.09	Current
TB 077	TB 237	Product recall notice – Installer notification – Buderus 500 and 600 domestic boiler series	25.08.09	Current
TB 078	TB 242	Vaillant ecoMAX and ecoTEC ranges of boilers – product modification and servicing reminder	01.04.09	Current
				(Under review)
TB 079	TB 162	BS 5482-1:2005 LPG Installations – Additional Guidance	01.04.09	Current
TB 080	TB 163	Changes to LPG regulator Standards	01.04.09	Current
TB 081	TB 167	Electricity at Work Regulations 1989 (Statutory Instrument No 1988/635)	01.04.09	Current
TB 082	TB 171	Discharging condensate into cast-iron waste systems	01.04.09	Current
TB 083	TB 239	Domestic Bulk Liquefied Petroleum Gas Market Investigation Order - 2008	01.04.09	Current
TB 084	TB 175	The prohibition of two pliable connectors on a domestic gas meter installation	22.09.09	Current

TB No.	Formerly	Gas Safe Register Technical Bulletin Index	Publication Date	Status
TB 085	TB 240	Subject BEKO gas cooker product range modification	01.04.09	Current
TB 086	TB 241	GDHA gas cooker product range modification	01.04.09	Current
TB 087	TB 178	Warm air heaters - change to spillage testing requirements	01.04.09	Current
TB 088	TB 183	Flueless Gas Fires – the importance of correct installation and commissioning	01.04.09	Current
TB 089	TB 186	Requesting a natural gas supply to a domestic property	01.04.09	Current
TB 090	TB 187	Loctite 55 pipe sealing cord – suitability for use on gas work	01.04.09	Current
TB 091	TB 188	Decommissioning part of a combined appliance	01.04.09	Current
TB 092	TB 190	Domestic ducted warm air heaters and systems – gas safety checks	01.04.09	Current
TB 093	TB 191	An overview of the revised Catering Information Sheet 23 Gas safety in catering and hospitality	26.10.09	Current
TB 094	TB 192	Tightness testing of an existing domestic natural gas MP-fed installation without an MIV	01.04.09	Current
TB 095	TB 193	Effect of extract fans on open-flued appliances	01.04.09	Current
TB 096	TB 194	Confirmation of FSD functionality for central heating boilers, water heaters and ducted warm air heaters	01.04.09	Current
TB 097	TB 195	Possible damage to backplate strapped fittings and gas escapes from self-sealing connectors (cooker bayonets)	01.04.09	Current
TB 098	TB 196	Vaillant ecoTEC range of boilers – product modification	01.04.09	Current
				(Under review)
TB 099	TB 197	Glow-worm Micron range of boilers – Important safety notice	01.04.09	Current
TB 100	TB 198	Dealing with damaged pre-fabricated built-in domestic gas meter boxes	01.04.09	Current
TB 101	TB 230	HSE Safety Alert – Risks from redundant solid fuel back boilers	01.04.09	Current
TB 102	TB 202	Location of Protective Equipotential Bonding on Gas Installation Pipework	01.04.09	Current
TB 103	TB 203	The application of the BS 7967 suite of Standards – The investigation of a report of fumes, smells,	01.04.09	Current
		spillage/leakage of combustion products, or CO detector activation		
TB 104	TB 205	The installation of thermoplastic CWSC and the safety of immersion heaters	01.04.09	Current
TB 105	TB 206	Non room-sealed appliances located in sleeping accommodation	01.04.09	Current
TB 106	TB 207	Corrosion protection of gas installation pipework using grease impregnated tape	01.04.09	Current
TB 107	TB 208	Glow-worm updated combustion tolerances	01.04.09	Current
TB 108	TB 209	Ideal Boilers – Information Bulletin	01.04.09	Current
TB 109	TB 212	European Directive for the Energy Performance of Buildings – Article 8 – providing energy efficiency	01.04.09	Current
		advice on heating and hot water systems		
TB 110	TB 213	Tightness testing domestic sized gas installations with G10/U16, G4/U6 and E6 gas meters	01.04.09	Current
TB 111	TB 215	The use of anaerobic compound as a bonding agent to join copper pipework to copper capillary fittings conveying gas	01.04.09	Current
TB 112	TB 216	Obtaining a meter index reading on a Landis + Gyr Libra 210 meter	01.04.09	Current
TB 113	TB 217	Research into available ventilation in modern floor voids	01.04.09	Current
TB 114	TB 219	Responding to a request to attend to flood damaged gas appliances and pipework	01.04.09	Current
TB 115	TB 238	Worcester condensing boilers – Inlet gas pressures – Amendment to installation instructions	01.04.09	Current

TB No.	Formerly	Gas Safe Register Technical Bulletin Index Subject	Publication Date	Status
TB 116	TB 222	Always use the appliance manufacturer's specified spare parts when replacing gas controls	01.04.09	Current
TB 117	TB 223	The dangers of cables buried in walls and partitions	01.04.09	Current
TB 118	TB 225	Safe electrical isolation of gas appliances	01.04.09	Current
TB 119	TB 226	Electrical safety requirements for gas appliances installed in rooms or spaces containing baths or showers	01.04.09	Current
TB 120	TB 227	The use of corrugated stainless steel semi-rigid gas piping in domestic and non-domestic installations	01.04.09	Current
TB 121	TB 229	Contractor responsibilities when disconnecting and reconnecting gas cooking appliances fitted with a	01.04.09	Withdrawn
		bayonet fitting, or other self-sealing connectors		See TB 025
TB 122	TB 176	Approved Document P – Electrical Safety – Dwellings	01.04.09	Current
TB 123	TB 234	Replacement room-sealed appliances for SE Duct and U Duct chimney systems	01.04.09	Current
TB 124	TB 236	LPG on boats, yachts & other vessels - Update on gas tightness testing, system pressure gauges and regulators	01.04.09	Current
TB 125	-	Health and safety guidance to be made available for no cost online	22.09.09	Current
TB 126	-	Combustion performance information for condensing boilers incorporating air/gas ratio control valve technology	06.11.09	Current
TB 999	-	Gas Safe Register Normative Document List	01.09.09	Current

+ -000-