



Alba Building Sciences Ltd

Norham, Perth Road, Blairgowrie, PH10 6EJ

www.albasciences.com

CERT Demonstration Action UK Park Homes

SCHEME REF: SSEN09132

Alba Report 21050


Appendix 8A

Post-Improvement Monitoring


Temperature Data

Blue Flag AP 31 – AP 40


AP 31 : Post-Improvement Internal Temperatures (°C)




AP 32 : Post-Improvement Internal Temperatures (°C)




AP 33 : Post-Improvement Internal Temperatures (°C)




AP 34 : Post-Improvement Internal Temperatures (°C)




AP 35 : Post-Improvement Internal Temperatures (°C)




AP 36 : Post-Improvement Internal Temperatures (°C)




AP 37 : Post-Improvement Internal Temperatures (°C)



AP 38 : Post-Improvement Internal Temperatures (°C)



AP 39 : Post-Improvement Internal Temperatures (°C)



AP 40 : Post-Improvement Internal Temperatures (°C)

